


## Controllers

Compact & affordable liquid level control.



### Mini Level Controller System

**Mini Level Controller HI 7873**  
Idea for liquid level control over distances of up to 1000'. Features high & low level control and overflow alarm. Requires HI 7874, HI 7164 & HI 731324.

**Bar Holder w/Amplified Circuitry HI 7873**

**Undecal Connector HI 7873**

**Threaded Measuring Bars HI 731324**

## Advanced Testers

HANNA advanced testers feature waterproof, floating casings & Automatic Temperature Compensation (ATC).

### Combination

#### Combo Waterproof pH/EC/TDS Temperature Tester

HI 98129

Measures 0.00 to 14.00 pH, 0 to 3999  $\mu$ S/cm (EC) & 0 to 2000 ppm (TDS). Features replaceable pH electrode cartridge & dual level LCD.

#### Combo Waterproof pH/EC/TDS Temperature Tester

HI 98130

Measures 0.00 to 14.00 pH, 0.00 to 20.00 mS/cm (EC) & 0.00 to 10.00 ppt (TDS). Features replaceable pH electrode cartridge & dual level LCD.

### Conductivity

#### DiST® 5 Waterproof EC/TDS

Temperature Tester HI 98311

Features replaceable graphite EC Probe cartridge & dual level LCD. Measures 0 to 3999  $\mu$ S/cm (EC) & 0 to 2000 ppm (TDS).



## Temperature Testers

Most HANNA thermometers feature HANNA's exclusive **CAL-Check** Auto Calibration Test.

*\*F & Factory calibration certificates are available*

#### Checktemp® 1 w/Remote Stainless Steel Probe HI 98509

Features a 6.29 x 0.12" stainless steel probe & measures -50.0 to 150.0°C.



## Calibration Solutions

HANNA single use calibration sachets provide the assurance of an accurate calibration everytime.

### EC

12.88 mS/cm solution HI 70030P\*

14.13  $\mu$ S/cm solution HI 70031P\*

### pH

pH 4 & 7 solution kit HI 77400P\*\*

### EC & pH

14.13  $\mu$ S/cm & pH 7 solution kit HI 77100P\*\*

### TDS & pH

1500 ppm & pH 7 solution HI 77200P\*\*

\* (25) 20 mL sachets

\*\* (20) 20 mL sachets, 10 per value



## Portable Meters

HANNA portable meters offer accurate results in the field.



### pH/EC/TDS

**3-in-1 Meter HI 9810**

Measure 3 of the most crucial parameters in printing with a single probe! Measures 0.00 to 14.00 pH, 0 to 6000  $\mu$ S/cm (EC) & 0 to 3000 ppm (TDS).



### Hygrometer


**Compact, Portable**

**Thermo-hygrometer HI 93640**

Features a built-in, thin-film capacitor sensor and dual temperature range. Measures 5.0 to 95.0% RH, 0.0 to 60.0°C & 32 to 140°F.

## Indicators

Professional instruments to monitor pH & conductivity of fountain solutions.



### Waterproof Indicator with Dual-level Backlit LCD

**pH/EC/TDS/Temp. Indicators**

HI 981404N Extra large display w/12 VDC power supply. Measures 0.0 to 14.0 pH, 0 to 3999  $\mu$ S/cm & 0 to 2000 ppm.

HI 981405N Extra large display w/12 VDC power supply. Measures 0.0 to 14.0 pH, 0.00 to 20.00 mS/cm & 0.00 to 10.00 ppt.